

Message

From: Doug Fritsch [dfritsch@greenleaf-power.com]
Sent: 8/17/2022 8:17:25 PM
To: AEO_R9 [AEO_R9@epa.gov]; brahblatt.roshni@epa.go
Subject: Excess Emissions Exceedance Report
Attachments: 20220817162738388.pdf

Roshni,

We experienced a CO lbs/hr exceedance during a boiler start up. Because we were in a start up our O2 was high and combustion wasn't stable. Once we started burning biomass our O2s dropped causing the CO lbs/hr to drop as well. Attached is the Form 500-N

Thank you,
Doug

Doug Fritsch
Operations Manager
Desert View Plant
Greenleaf Power, LLC
(760) 262-1682 office
(979) 702-9428 cell
Dfritsch@greenleaf-power.com

